

Oil Field Environmental Incident Summary

Incident: 20140914154803 **Date/Time of Notice:** 09/14/2014 15:48

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: WAYZETTA 44-0311H

Field Name: PARSHALL

Well File #: 26459

Date Incident: 9/13/2014 **Time Incident:** 20:30

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 90

Sec: 3

Qtr:

Location Description:

Submitted By: Matt Richards

Received By:

Contact Person: Matt Richards
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Standing liquid was sucked up and put into tanks. Hydrovac power washed tanks and surrounding rocks to push oil into sump hole. Contaminated soil will be kept on site till trucks can come to haul off to clean harbors disposal.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 9/15/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a tank overflow, apparently outside of the tank berm, remained on location according to the report. NDIC retains oversight.